




INSPECTION OF ALUMINIUM PROFILES

Mistakes are
difficult to
detect



Wrong orientation of
a part



Wrong part used



Bad insertion of
profile

INSPECTION OF ALUMINIUM PROFILES

The solution: Image recognition with visual feedback

